

Queens road play area Chester

Inspection Start: 08 July 2025 at 10:01 am

Inspected By: -



Winsford Town Council

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Access/pathways	No Hazard	None	None
General surface	No Hazard	None	None
Access gates	No Hazard	None	None
Litter bins	No Hazard	None	None
Fencing	No Hazard	None	None
Seats	Needs Adjusting	Low	Adjust
Seats are little lose and needs to be adjusted			
Maintance gate	No Hazard	None	None
Ownership/signage	No Hazard	None	None

Queens road play area Chester

Equipment



Winsford Town Council

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Roundabout	No Hazard	None	None
2 springers	No Hazard	None	None
Seesaw 2	Needs Adjusting	Medium	Adjust
Side bolts on both seesaws feel loose these need to be tightened up			
Spare	-	-	-
Spare	-	-	-
Spare	-	-	-
	-	-	-
	-	-	-

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Grass mats	No Hazard	None	None
Picnic tables	No Hazard	None	None
		-	
cradle swing	-	-	-
		-	
Swing flat	-	Low	Monitor
Bushes on all the swings need to be monitored as these are starting to ware but don't need replacing			
Talk tubes x2	-	-	-
		-	
Toddler multiplay unit	-	-	-
		-	
Basketball post	No Hazard	None	None
MUGA	No Hazard	None	None
BMX track josh jump	Needs Repairing	Medium	Repair
This has been on the report for a while few chunks have been taken out on the track needs repair			

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Spare	-	-	-
Spare	-	-	-
		-	
Spare	-	-	-
		-	
Spare	-	-	-
Spare	-	-	-
		-	
Spare	-	-	-
		-	
Spare	-	-	-
Spare	-	-	-
		-	
Spare	-	-	-

Photo 1:



Photo 2:



Photo 3:



Photo 4:



Photo 5:



Photo 6:





Authorised By: -

Immediate Action: -

Inspection Completed: 08 July 2025 at 10:21 am

Signature:

Addition comments:

Location:

